


CLUB CLB100

INSTALLATION DIAGRAM

COL COLUMN DISPENSER OPTION



Please Note: If the appliance is installed in a closed cupboard space, large adequate ventilation is required to validate the warranty

N.B. When trimming tubes to length - to ensure NO LEAKS use a sharp tube cutter for a clean cut















205